
Track 230V Power Wire Cutting Tool


13814100


1 CUT THE TRACK WITH EXACT PERPENDICULAR FINISH



2 PLACE THE CUTTING TOOL WITH THE INSULATION TO THE OUTSIDE OF THE TRACK AND CUT THE 4 COPPER WIRES

(middle dali coppers do not require cutting)





3 COMPLETED AND READY FOR FURTHER INSTALLATION

